

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: FV Wild Coho

SITREP #: 2

SPILL NUMBER: 04119903401

LEDGER CODE: 1951360

TIME/DATE OF SPILL: The spill occurred when the boat sank between 06:30 and 07:00 AM, on February 3, 2004. ADEC was notified by the Yakutat ADF&G office at 8:45 AM, February 3, 2004.

TIME/DATE OF SITUATION REPORT: 12:00 PM, February 4, 2004

TIME/DATE OF THE NEXT REPORT: This is the final report.

TYPE/AMOUNT OF PRODUCT SPILLED: 160-180 gallons of diesel and 2-3 gallons of lube oil were aboard the vessel when it sank. This is a revised estimate from Sitrep 1, as per the owner.

LOCATION: Yakutat small boat harbor, Yakutat.

CAUSE OF SPILL: Vessel sank at the dock during a period of heavy snowfall. The cause is still under investigation.

POTENTIAL RESPONSIBLE PARTY (PRP): Mr. Bill Lucey, Yakutat, Alaska.

RESPONSE ACTION: The owner set sorbent boom over the sunken vessel initially. 400 feet of 20" containment boom and other supplies from the ADEC response equipment container in Yakutat were used in the response. An ADEC responder from Juneau was on site to monitor and assist in the response. The vessel was successfully raised using heavy equipment onboard a landing craft in the late afternoon of February 3rd. ADEC coordinated the response with USCG Marine Safety Office in Juneau.

SOURCE CONTROL: The vessel was successfully re-floated in the afternoon of February 3rd.

RESOURCES AFFECTED: Yakutat small boat harbor. ADEC has received no reports of oiled wildlife.

FUTURE PLANS AND RECOMMENDATIONS: The ADEC responder will give instructions for decontamination and cleaning of the ADEC boom and replacement of sorbent materials from the ADEC response container utilized in the response. The ADEC responder will return to Juneau this evening. The investigation as to the cause of the sinking is continuing.

WEATHER: 32°F snow. Rain and breezy in the afternoon, highs around 36°, east winds 15 mph, becoming southeast 15 to 25 mph in the afternoon.

UNIFIED COMMAND AND PERSONNEL:

Incident Commander:	Mr. Bill Lucey (PRP)
F.O.S.C.:	CDR John Sifling (USCG)
S.O.S.C.:	Bob Mattson (ADEC)
Field S.O.S.C.:	Scot Tiernan (ADEC)

FOR ADDITIONAL INFORMATION CONTACT: Bob Mattson, ADEC at 465-5349. Photos and other spill information will be made available on February 5th for viewing at <http://www.state.ak.us/dec/spar/perp/index.htm>

AGENCY/STAKEHOLDER NOTIFICATION LIST

Agency	Name	Sent Via	Additional Info	Telephone	Fax
ADFG	Mark Fink	Email	Spill Report Group	267-2338	267-2464
ADNR Habitat	Catherine Poh.	Email	Spill Report Group	465-4182	465-4272
ADNR	Sam Means	Email	Spill Report Group	269-8546	269-8913
ADNR	Doug Sanvik	Email	Spill Report Group	465-3400	465-3513
USCG (MSO Juneau)	CDR John Sifling	Email	jsifling@cgalaska.uscg.mil	463-2453	463-2445
USCG (MSO Juneau)	Lt. Tyrone Jones	Email	tjones@cgalaska.uscg.mil	463-2470	463-2445
EPA	Matt Carr	Email	Spill Report Group	271-3616	271-3424
NMFS	Jon Kurland	Email	Jon.kurland@noaa.gov	586-7638	586-7358
Other	Name	Sent via	Additional Info	Telephone	Fax
Senate/ Dist. C	Georgianna Lincoln	Fax	Session: Interim:	465-3732 888-461-3732	465-2652 465-2652
House/ Dist. 5	Albert Kookesh	Fax	Session: Interim:	465-3473 788-3501	465-2827 788-3176
City & Borough of Yakutat Mayor	Victoria Demmert	Fax		784-3323	784-3281
SEAPRO	Dave Owings	Fax	dave@seapro.org	225-7002	247-1117




Figure 1 Location of the sinking of the FV Wild Coho and of the ADEC Response Container in Yakutat, Alaska.