

**ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION**  
**Division of Spill Prevention and Response**  
**Prevention and Emergency Response Program**

**SITUATION REPORT**

**INCIDENT NAME:** Barge Selma S

**SITREP #:** 4 and Final

**SPILL NUMBER:** 06269915301

**LEDGER CODE:** 14207360

**TIME/DATE OF SPILL:** Unknown, however the spill was discovered as sheen around the wooden vessel the morning of May 15, 2006. The spill was reported to ADEC at 8:23 a.m., May 15, 2006 (revised from May 16, 2006) by the Aleknagik Village EPA Indian General Assistance Program (IGAP) Coordinator.

**TIME/DATE OF SITUATION REPORT:** 12:00 PM, August 31, 2006

**TIME/DATE OF THE NEXT REPORT:** This is the final report

**TYPE/AMOUNT OF PRODUCT SPILLED:** Diesel fuel, PRP estimates 50 gallons, based on the initial release rate from vessel up to controlling the source.

**LOCATION:** Approximately 2 miles downriver from Aleknagik Lake on the Wood River. The Wood River is located 16 miles northwest of Dillingham.

**CAUSE OF SPILL:** PRP believes that the spill may have been related to the keel freezing to the river bottom, and incoming tide later lifting the hull off the wooden keel.

**POTENTIAL RESPONSIBLE PARTY (PRP):** Anna Mae Sorenson., Owner

**RESPONSE ACTION:** On June 5, 2006 the PRP reported to ADEC that all the remaining fuel was removed from the barge and no further oil sheening observed at the site. On June 24, 2006, the PRP submitted a final report to ADEC indicating that all fuel had been removed from the barge. The PRP plans to replace all dispensable items used for the spill response from the ADEC emergency spill conex in Dillingham.

**SOURCE CONTROL:** Successfully removed fuel from remaining non-leaking fuel tank. Engine oils from the main and auxiliary engines will be removed during the planned dismantling of the vessel (presently on PRP's private property).

**RESOURCES AFFECTED:** Wood River and confluence of Aleknagik Lake. There have been no reports of any impacted wildlife or recent oil sheens from the vessel.

**FUTURE PLANS AND RECOMMENDATIONS:** ADEC has reviewed PRP's vessel removal plan included in their final report. The PRP plans on disassembling the vessel on their property since it is inoperable. ADEC plans on making spill site visits to Dillingham in October.

**WEATHER:** Numerous showers in the morning and mostly cloudy with scattered showers in the afternoon. Highs in the lower 60s, north wind 15 to 30 mph.

**UNIFIED COMMAND AND PERSONNEL:**

Incident Commander:	Rick Halford, Owner Representative
F.O.S.C:	Captain Mark DeVries, USCG
S.O.S.C:	Gary Folley, ADEC

**FOR ADDITIONAL INFORMATION CONTACT:** Frank Wesser, phone: 269-3062.

Photographs and other spill information are available for viewing at:

<http://www.state.ak.us/dec/spar/perp/index.htm>

**AGENCY/STAKEHOLDER NOTIFICATION LIST**

This sitrep has been distributed via email to the Governor's office, ADF&G, ADNR, SECC, USEPA, USDOJ, NMFS, USFWS, and USFS in addition to the following.

<b>AGENCY</b>	<b>NAME</b>	<b>Sent Via</b>		<b>Telephone</b>	<b>Facsimile</b>
USCG-MSO/ANC	USCG-Office	Fax		271-6700	271-6751
USEPA	Matt Carr	Fax		271-3616	271-3424
<b>OTHER</b>	<b>NAME</b>	<b>Sent Via</b>		<b>Telephone</b>	<b>Facsimile</b>
Aleknagik City Administrator	Patty Heyano				842-2107
Native Village of Aleknagik	Wassillie Ilutsik, President			842-2080	842-2081
Aleknagik Natives Ltd.	Bobby Andrew, President			842-2385	842-1662
BBNA	Susan Flensburg	Email	sflensburg@bbna.com	842-5257	842-5862
Bristol Bay Borough	Fred Pike	Email	manager@theborough.com	246-4224	246-6633
			<b>Session/Interim</b>		
<b>Senate S/ Bethel</b>	Lyman Hoffman	Fax	Bethel 5/16 - 1/09 Juneau 1/10 - 5/15	543-3541 465-4453	543-3542 465-4523
<b>House 37/ Bethel</b>	Carl Moses	Fax	Bethel 5/16 - 1/09 Juneau 1/10 - 5/15	486-4942 465-4942	465-4589 465-4589